

Plymouth Doctor
RESTORATION PARTS
NEW FOR YOUR 1937 – '39 PLYMOUTH!

1. INNER ROCKER PANEL (2dr Sedan & Coupe Only)	\$ 63
2. OUTER ROCKER PANEL, (2dr Sedan & Coupe)	\$ 177
3. INNER ROCKER PANEL, (CONVERTIBLE ONLY)	\$ 63
4. OUTER ROCKER PANEL, (CONVERTIBLE ONLY)	\$ 195
5. INNER ROCKER PANEL (4DR SEDAN)	\$ 63
6. OUTER ROCKER PANEL (4DR SEDAN)	\$ 177
7. MAIN CABIN FLOOR, RIGHT OR LEFT SIDE	\$ 370
8. REAR KICK PLATE (MAIN CABIN TO TRUNK)	\$ 105
9. DRIVE SHAFT TUNNEL	\$ 105
10. MAIN CABIN FLOOR REPLACEMENT KIT (Includes: #7 R&L, 8 & 9)	\$ 875
11. MAIN CABIN FLOOR FRONT REPAIR SECTION (1937 – '38 Only)	\$ 360
12. MAIN CABIN FLOOR FRONT REPAIR SECTION (1939 Only)	\$ 360
13. FRONT FLOOR PAN (ALL EXCEPT CONVERTIBLE & 7 PASS SDN)	\$ 377
14. TOE BOARD	\$ 377
15. TRUNK FLOOR PAN (AS ORIGINAL), COMPLETE, SEDAN	\$1,700 *
16. TRUNK FLOOR PAN (AS ORIGINAL), COMPLETE, COUPE	\$1,425 *
17. TRUNK FLOOR REPAIR SECTION (REAR 24")	\$ 375
18. TRUNK LID INNER BOTTOM REPAIR SECTION (TRUNK SEDAN ONLY)	\$ 353
19. TRUNK LID, OUTER BOTTOM REPAIR SECTION (TRUNK SEDAN ONLY)	\$ 250
20. DECK LID, INNER BOTTOM REPAIR SECTION (COUPE/CONVERTIBLE)	\$ 353
21. DECK LID, OUTER BOTTOM REPAIR SECTION (COUPE/CONVERTIBLE)	\$ 250
22. INNER WHEEL HOUSE ASSEMBLY, COMPLETE (ORIGINAL STYLE)	\$ 600
23. INNER WHEEL HOUSE REPAIR SECTION	CALL
24. OUTER DOOR REPLACEMENT PANEL (4dr SEDAN – FT. ONLY)	\$ 283
25. OUTER DOOR REPLACEMENT PANEL (2dr SEDAN & COUPE – FT. ONLY)	\$ 344
26. OUTER DOOR LOWER REPAIR PANEL (CPE, SEDAN – FT. ONLY)	\$ 118
27. DOOR FRAME BOTTOM REPAIR SECTION (CPE, SEDAN – FT. ONLY)	\$ 105
28. DOOR FRAME BOTTOM REPAIR PANEL, FULL (CPE, SEDAN – FT ONLY)	\$ 118
29. DOOR FRAME LOWER REPAIR PANEL (CPE, SEDAN – FT. ONLY)	\$ 85
30. QUARTER TO FLOOR EXTENSION (CPE, 2DR SEDAN)	\$ 102
31. OUTER QUARTER PANEL REPAIR SECTION (ALL EXC 4DR SEDAN)	\$ 145
32. LOCK PILLAR REPAIR SECTION	\$ 118
33. LOWER REAR BODY SIDE PANEL CORNER REPAIR SECTION	\$ 118
34. LOWER OUTER REAR BODY PANEL (TRUNK SEDAN)	\$ 375
35. LOWER OUTER REAR BODY PANEL (TRUNK COUPE ONLY)	\$ 355
36. LOWER INNER REAR BODY PANEL REINFORCEMENT (CPE ONLY)	\$ 118
37. LOWER INNER REAR BODY PANEL REINFORCEMENT (SEDAN ONLY)	\$ 118
38. LOWER COWL REPAIR SECTION (ALL)	\$ 105
39. COWL REPAIR PANEL, FULL (ALL)	\$ 175
40. BATTERY BOX ASSEMBLY, COMPLETE	\$ 250
40. BATTERY BOX BOTTOM ONLY	\$ 110
42. BATTERY BOX COVER ONLY	\$ 125
43. BATTER BOX COVER INSPECTION PLATE ONLY	\$ 40
44. FIREWALL – STREE ROD ONLY	\$ 225

*NOTE: ALL ITEMS MARKED WITH AN * REQUIRE SHIPPING BY TRUCK

- ALL PARTS ARE FABRICATED IN 18ga AND ARE CHECKED FOR ACCURACY USING AN UNDAMAGED ORIGINAL PART AS A GUIDE.

CONTACT THE *Plymouth Doctor* AT:
517-675-5717 or E-Mail: plymouthdoctor@netscape.net