

Plymouth Doctor Restoration Parts
STEEL RESTORATION PARTS
NEW FOR YOUR 1942 - FIRST SERIES 1949 Plymouth!

Body Group	Part Number	Description	Application	Cost Each	REMARKS
Outer Body Repair & Replacement Panels					
1	P15-1001-L	Lower Front Body Side Panel Repair Section, Left	Coupe, Convertible, 2dr Sedan	\$ 119	Fits between the back of the door & rear fender
	P15-1001-R	Lower Front Body Side Panel Repair Section, Right	Coupe, Convertible, 2dr Sedan	\$ 119	
	P15-1002-L	Lower Rear Body Side Panel Repair Section, Left	Coupe, Convertible, 2dr Sedan	\$ 118	Fits below the tail lamp assembly
	P15-1002-R	Lower Rear Body Side Panel Repair Section, Right	Coupe, Convertible, 2dr Sedan	\$ 118	
	P-15-1003-L	Lower Outer Door Panel Repair Section, Lt, Front	Coupe, Convertible, 2dr Sedan	\$ 225	Replaces the lower 8" of the outer front door panel
	P-15-1003-R	Lower Outer Door Panel Repair Section, Rt Front	Coupe, Convertible, 2dr Sedan	\$ 225	
	P-15-1004-L	Outer Door Replacement Panel, Lt. Front	Coupe, Convertible, 2dr Sedan	\$ 344	Replaces up to the bottom of the side glass opening
	P-15-1004-R	Outer Door Replacement Panel, Rt. Front	Coupe, Convertible, 2dr Sedan	\$ 344	
	P-15-1005-CO	Outer Deck Lid Repair Section	Coupe, Convertible	\$ 299	Replaces the bottom 6" of the trunk lid or deck lid
	P-15-1006-CI	Inner Deck Lid Repair Section	Coupe, Convertible	\$ 225	Replaces the bottom 6" of the inside of the deck lid
	P-15-1007-SO	Outer Trunk Lid Repair Section	2 & 4dr Sedan Only	\$ 225	Replaces the bottom 6" of the inside of the trunk lid
P-15-1007-SI	Outer Trunk Lid Repair Section	2 & 4dr Sedan Only	\$ 299	Replaces the bottom 6" of the trunk lid or deck lid	
Structural Replacement Panels and Sections					
2	P15-2001-L	Upper Sill Plate, Left	Coupe, Convertible, 2dr Sedan	\$ 119	Covers the top of the Inner & Outer Rockers
	P15-2001-R	Upper Sill Plate, Right	Coupe, Convertible, 2dr Sedan	\$ 119	
	P15-2002-L	Upper Sill Plate Extension, Left	Coupe, Convertible, 2dr Sedan	\$ 49	Extends the Upper Sill Plate beyond the door opening
	P15-2002-R	Upper Sill Plate Extension, Right	Coupe, Convertible, 2dr Sedan	\$ 49	
	P15-2002-CUR	Upper Sill Plate Cover, Rt	Coupe, Convertible, 2dr Sedan	\$ 105	Covers the upper sill plate & provides for use of scuff plate
	P15-2002-CUL	Upper Sill Plate Cover, Lt	Coupe, Convertible, 2dr Sedan	\$ 105	Covers the upper sill plate & provides for use of scuff plate
	P15-2002-SUR	Upper Sill Plate Cover, Rt	4dr Sedan	\$ 105	Covers the upper sill plate & provides for use of scuff plate
	P15-2002-SUL	Upper Sill Plate Cover, Lt	4dr Sedan	\$ 70	Covers the upper sill plate & provides for use of scuff plate
	P15-2003-L	Outer Rocker Panel, Left	Coupe, Convertible, 2dr Sedan	\$ 143	Installs from the cowl pillar to the lock pillar
	P15-2003-R	Outer Rocker Panel, Right	Coupe, Convertible, 2dr Sedan	\$ 143	Installs from the cowl pillar to the lock pillar
	P15-2004-L	Outer Rocker Panel, Extension, Left	Coupe, Convertible, 2dr Sedan	\$ 49	Extends the Outer Rocker beyond the door opening
	P15-2004-R	Outer Rocker Panel, Extension, Right	Coupe, Convertible, 2dr Sedan	\$ 49	Extends the Outer Rocker beyond the door opening
	P15-2005-L	Inner Rocker, Left	Coupe, Convertible, 2dr Sedan	\$ 133	Attaches the floor to the Outer Rocker
	P-15-2005-R	Inner Rocker, Right	Coupe, Convertible, 2dr Sedan	\$ 133	Attaches the floor to the Outer Rocker
	P15-2006-L	Inner Rocker Extension, Left	Coupe, Convertible, 2dr Sedan	\$ 49	Extends the Inner Rocker past the door opening
	P-15-2006-R	Inner Rocker Extension, Right	Coupe, Convertible, 2dr Sedan	\$ 49	Extends the Inner Rocker past the door opening
	P-15-2008	Lower Trunk Sill Repair Section	All Models	Call	Replaces the trunk floor at the striker plate
	P-15-2009-L	Lower Cowl Repair Section, Left	All Models	Call	Replaces the lower 8 inches of the cowl
	P-15-2009-R	Lower Cowl Repair Section, Right	All Models	Call	Replaces the lower 8 inches of the cowl
	P-15-2010-L	Lower Door Frame Repair Section, Left	Coupe, Convertible, 2dr Sedan	\$ 105	Replaces the bottom of the door frame
P-15-2010-R	Lower Door Frame Repair Section, Right	Coupe, Convertible, 2dr Sedan	\$ 105	Replaces the bottom of the door frame	
Floor Panels					
3	P-15-3001	Front Floor Panel, Center	All Except Convertible	\$ 475	Covers front floor from the firewall to leading edge of the Main Cabin Floor
	P-15-3001-1L	Front Floor Panel, Extension, Left	All Except Convertible	\$ 140	Replaces bolt in floor section to the left of Front Floor Center Panel
	P-15-3001-1R	Front Floor Panel, Extension, Right	All Except Convertible	\$ 140	Replaces bolt in floor section to the right of Front Floor Center Panel
	P-15-3002-L	Front Floor Panel Repair Section, Left	All Except Convertible	\$ 190	Covers the foot well area from cowl to transmission hump
	P-15-3002-R	Front Floor Panel Repair Section, Right	All Except Convertible	\$ 190	Covers the foot well area from cowl to transmission hump
	P-15-3003-L	Main Cabin Floor, Left	All Except Convertible	\$ 349	Covers the left side from the front floor pan to rear of back seat
	P-15-3003-R	Main Cabin Floor, Right	All Except Convertible	\$ 349	Covers the right side from the front floor pan to the rear of back seat
	P-15-3004	Drive Shaft Tunnel	All Except Convertible	\$ 145	Replaces the tunnel from the front floor to the trunk floor
	P-15-4001	Trunk Floor w/Spare Tire Well	All Except Convertible	\$ 1,550	Replaces the entire trunk floor - includes holes for body mounts
	P-15-4002	Spare Tire Well	All Models	\$ 325	Replaces entire spare tire well area - as original
	P-15-4000-P	Interior Floor Package	All Except Convertible	\$ 1,350	Includes all interior floor components

