

1933 - 1935 (First Series) Dodge Pickup Trucks

Outer Repair Panels

Part Name	Description	Photo #
Door Panel, Outer Repair Section	Replaces the lower 6" of Outer Door Panel	1H & 1I
Door Panel, Outer Replacement Panel	Replaces the Outer Door Panel to within 1" of the window opening	1J1 & 1J2
Cab Corner	Replaces cab lower corner, includes reveal	1F
Cab Rear Reveal	Replaces cab lower 8", includes reveal	1B & 1E
Cowl Repair Section	Replaces the lower 6" of the cowl	1G
Rocker, Outer	Replaces entire Outer Rocker as original	2A
Side Splash Apron	Replaces Side Splash Apron as Original	Page 5

Inner Cab Structure Components

Door Frame Bottom Repair Section	Replaces the bottom of the door frame	2B
Sub Frame Rail	Replaces entire inner body to frame structure - one side	2A
Rear Cross Member	Replaces entire rear body cross member at back of cab	1B,1D,1E
Cab Rear Reveal Weld Strip	Provides interior welding area for exterior panel	1D & 1E

Price Each	
\$	78
\$	283
\$	196
\$	196
\$	118
\$	196
\$	392
\$	118
\$	392
\$	196
\$	118