

1939 - 1947 Dodge & Plymouth Pickup Trucks

Outer Repair Panels

Part Name	Description	Price Each
Door Panel, Outer Repair Section	Replaces the lower 6" of Outer Door Panel	\$ 109
Door Panel, Outer Repair	Replaces the outer panel from belt line to hem flange	\$ 299
Cab Corner	Replaces cab lower corner	\$ 175
Cab Rear Reveal	Replaces cab lower 8"	\$ 175
Cowl Repair Section	Replaces the lower 6" of the cowl	\$ 118
Rocker, Outer	Replaces entire Outer Rocker as original	\$ 196
Side Splash Apron	Replaces Side Splash Apron as Original	\$ 210

Inner Cab Structure Components

Door Frame Bottom Repair Section	Replaces the bottom of the door frame	\$ 118
Sub Frame Rail	Replaces entire inner body to frame structure - one side	\$ 392
Rear Cross Member	Replaces entire rear body cross member at back of cab	\$ 196
Cab Rear Reveal Weld Strip	Provides interior welding area for exterior panel	\$ 118