

# ***Plymouth Doctor***

## **STEEL RESTORATION PARTS**

**NEW FOR YOUR 1935 & '36 PLYMOUTH, DODGE AND CHRYSLER AIRSTREAM!**

INNER ROCKER PANEL (ALL 1935 EXCEPT CONV) (SPECIFY CPE OR 2DR SDN)	\$ 102 EA
OUTER ROCKER PANEL, FRONT (ALL 1935 EXCEPT CONV'T& 7 PASS SDN)	\$ 184 EA
OUTER ROCKER PANEL, (COUPE) '36 PLYMOUTH & DODGE ONLY	\$ 196 EA
INNER ROCKER PANEL, (COUPE) '36 PLYMOUTH & DODGE ONLY	\$ 95 EA
INNER ROCKER EXTENSION, FRONT (COUPE) '36 PLY & DODGE ONLY	\$ 105 EA
INNER ROCKER PANEL, REAR (ALL '35 PLYMOUTH & DODGE	\$ 75 EA
OUTER ROCKER PANEL, REAR, ALL 4DR SEDANS	\$ 90 EA
TOE BOARD, ALL	\$ 329
FRONT FLOOR PAN (ALL EXCEPT 7 PASSENGER SEDAN) 1936 Ply & Dodge Only	\$ 375
FRONT FLOOR PAN (ALL EXCEPT 7 PASSENGER SEDAN) 1935 Ply & Dodge Only	\$ 365
FRONT FLOOR PAN (ALL AIRSTREAM MODELS) 1936 Only	\$ 365
FRONT FLOOR PAN REPAIR SECTIONS (7 PASSENGER SEDAN)	\$ 140 EA
MAIN CABIN FLOOR, RIGHT OR LEFT SIDE	\$ 360 EA
MAIN CABIN FLOOR REPAIR SECTIONS	\$ 125 EA
DRIVE SHAFT TUNNEL	\$ 120
INNER QUARTER TO FLOOR EXTENSION	\$ 35 EA
TRUNK FLOOR PAN (AS ORIGINAL), COMPLETE (Includes Fuel Filler Tube Cover)	\$1,395 *
TRUNK FLOOR REPAIR SECTIONS	CALL
TRUNK FLOOR PAN (STREET ROD VERSION)	\$1,098*
FUEL FILLER TUBE COVER	\$ 150
INNER WHEEL HOUSE ASSEMBLY, COMPLETE	\$ 600 EA
INNER WHEEL HOUSE REPAIR SECTION	CALL
INNER WHEEL HOUSE ASSEMBLY, COMPLETE (STREET ROD)	\$ 225 EA
FRAME HORN HOUSING (FRONT FENDER EXTENSION)	\$ 175 EA
OUTER QUARTER PANEL REPAIR SECTION (ALL EXC 4DR SEDAN)	\$ 165 EA
OUTER QUARTER PANEL REPAIR SECTION, 4DR SDN (Dog Leg)	\$ 118 EA
OUTER DOOR REPLACEMENT PANEL (CPE, SEDAN - FT. ONLY)	\$ 285
OUTER DOOR LOWER PATCH PANEL (CPE, SEDAN - FT. ONLY)	\$ 118
DOOR FRAME BOTTOM REPAIR SECTION (CPE, SEDAN - FT. ONLY)	\$ 85
LOWER FRONT COWL REPAIR SECTION - ALL	\$ 109
LOWER OUTER REAR BODY PANEL (CPE, CONV, R/S CPE)	\$ 399
LOWER OUTER REAR BODY PANEL (FLATBACK SEDAN)	\$ 399
LOWER OUTER REAR BODY PANEL (TRUNK SEDAN) (1935 Only)	\$ 355
LOWER OUTER REAR BODY PANEL (TRUNK SEDAN) (1936 Only)	\$ 345
WINDSHIELD GARNISH MOLDING (ALL 1936 DELUXE EXCEPT CONV'T)	\$ 119 EA
BATTERY BOX ASSEMBLY, COMPLETE	\$ 250
BATTERY BOX BOTTOM ONLY	\$ 118
BATTERY BOX COVER ONLY	\$ 157
BATTERY BOX COVER INSPECTION PLATE ONLY	\$ 40
FIRE WALL (STREET ROD ONLY)	\$ 225
ROOF INSERT (COUPE)	\$ 325
RUMBLE SEAT STEP PAD FENDER REINFORCEMENT	\$ 176
EXTERNAL HORN FENDER MOUNTING BRACKETS (2 REQ'D)	\$ 118 EA
EXHAUST PIPE (ALUMINIZED) AS ORIGINAL	\$ 49
TAIL PIPE (ALUMINIZED) AS ORIGINAL	\$ 89
MUFFLER (ALUMINIZED) AS ORIGINAL	\$ 49

\*NOTE: ITEMS MARKED WITH AN \* REQUIRE SHIPPING BY TRUCK

**CALL OR E-MAIL THE *Plymouth Doctor* at:  
517-675-5717 or 517-285-3675 – [plymouthdoctor@netscape.net](mailto:plymouthdoctor@netscape.net)**