

## *Plymouth Doctor Restoration Parts*

**NEW STEEL REPLACEMENT PARTS FOR YOUR 1949 - 1952 *Plymouth - DeSoto - DODGE***

### OUTER BODY REPAIR & REPLACEMENT PANELS

LOWER DOOR REPAIR SECTION COUPE/CUT           \$ 165 EA	REPLACES THE LOWER 6" OF THE OUTER DOOR PANEL	
LOWER DOOR REPAIR SECTION 4DR SEDAN           \$ 118 EA	REPLACES THE LOWER 6" OF THE OUTER DOOR PANEL, FRONT	
LOWER DOOR REPAIR SECTION 4DR SEDAN           \$ 90 EA	REPLACES THE LOWER 6" OF THE OUTER DOOR PANEL, REAR	
LOWER DOOR REPAIR SECTION WAYFARER 2DR ONLY   \$ 165 EA	REPLACES THE LOWER 6" OF THE FRONT DOOR PANEL	
FULL DOOR REPLACEMENT PANEL \$ 325 EA	REPLACES THE PANEL UP TO BELT LINE	COUPE/CUT
FULL DOOR REPLACEMENT PANEL 2DR ONLY   \$ 325 EA	REPLACES THE PANEL UP TO BELT LINE	WAYFARER
FULL DOOR REPLACEMENT PANEL FRONT       \$ 310 EA	REPLACES THE PANEL UP TO THE BELT LINE	4DR SEDAN
FULL DOOR REPLACEMENT PANEL REAR        \$ 290 EA	REPLACES THE PANEL UP TO THE BELT LINE	4DR SEDAN
LOWER OUTER BODY SIDE PANEL REPAIR SECTION COUPE/CUT           \$ 119 EA	REPLACES LOWER FRONT CORNER OF THE BODY SIDE PANEL	
LOWER OUTER BODY SIDE PANEL REPAIR SECTION WAYFARER ONLY       \$ 175 EA	REPLACES LOWER FRONT CORNER OF THE BODY SIDE PANEL	
LOWER REAR BODY FINISH PANEL \$ 105 EA	REPLACES THE NARROW STRIP BETWEEN THE TRUNK & BUMPER	ALL
LOWER FRONT, REAR BODY SIDE PANEL 4DR SEDAN & SW ONLY   \$ 110 EA	REPLACES THE SECTION BETWEEN THE REAR DOOR & FENDER	
LOWER OUTER REAR BODY PANEL REVEAL ALL EXCEPT FAST BACK   \$ 288 EA	REPLACES AREA BELOW TRUNK LID - INCL. WEATHER STRIP CHANNEL	

### STRUCTURAL REPLACEMENT PANELS AND SECTIONS

UPPER SILL PLATE, FRONT \$ 119 EA	COVERS THE TOP OF THE INNER & OUTER ROCKERS	ALL MODELS
UPPER SILL PLATE, FRONT WAYFARER (CPE/SDN) \$ 119 EA	COVERS THE TOP OF THE INNER & OUTER ROCKERS	DODGE
UPPER SILL PLATE, FRONT WAYFARER ROASTER \$ NOT AVAILABLE	COVERS THE TOP OF THE INNER & OUTER ROCKERS	DODGE
UPPER SILL PLATE, REAR \$ 49 EA	COVERS THE TOP OF THE INNER & OUTER ROCKERS	ALL 4DR SDN
UPPER SILL PLATE EXTENSION COUPE MODELS \$ 49 EA	EXTENDS THE UPPER SILL PLATE BEYOND DOOR OPENING	ALL
OUTER ROCKER PANEL 2DR SDN \$ 143 EA	INSTALLS FROM THE COUL PILLAR TO THE LOCK PILLAR	CPE, CUT,
OUTER ROCKER PANEL CPE & SEDAN ONLY \$ 259 EA	INSTALLS FROM THE COUL PILLAR TO THE LOCK PILLAR	WAYFARER
OUTER ROCKER PANEL \$ 177 EA	INSTALLS FROM THE COUL PILLAR TO THE REAR LOCK PILLAR	4DR SDN
INNER ROCKER PANEL 2DR SDN \$ 133 EA	ATTACHES THE MAIN CABIN FLOOR TO THE OUTER ROCKER	CPE, CUT,
INNER ROCKER PANEL CPE & SEDAN ONLY \$ 56 EA	ATTACHES THE MAIN CABIN FLOOR TO THE OUTER ROCKER	WAYFARER
INNER ROCKER PANEL EXTENSION 2DR SDN \$ 49 EA	EXTENDS THE INNER ROCKER PANEL PAST DOOR OPENING	CPE, CUT,

### FLOOR PANELS AND REPAIR SECTIONS

TOE BOARD REPLACEMENT PANEL EXCEPT CUT \$ 550 EA	REPLACES ORIGINAL TOE BOARD (BOLT IN)	ALL
TOE BOARD REPLACEMENT PANEL WAYFARER CPE & SEDAN ONLY \$ 550 EA	REPLACES ORIGINAL TOE BOARD (BOLT IN)	
FRONT TOE BOARD REPAIRS SECTION ALL EXCEPT CUT \$ 290 EA	REPAIRS THE LOWER CORNER OF TOE BOARD W/INSPECTION COVER	

MAIN CABIN FLOOR REPAIR SECTION, FT. ALL EXCEPT CUT	\$ 315 EA	REPLACES RIGHT OR LEFT SIDE OF FRONT FLOOR PAN	
MAIN CABIN FLOOR REPAIR SECTION, RR. ALL EXCEPT CUT	\$ 315 EA	REPLACES RIGHT OR LEFT SIDE OF REAR FLOOR PAN	
DRIVE SHAFT TUNNEL ALL EXCEPT CUT	\$ 245 EA	REPLACES THE TUNNEL FROM FRONT FLOOR PAN TO TRUNK	
INTERIOR FLOOR REPAIR PACKAGE EXCEPT CUT	\$ 1,670	INCLUDES ALL INTERIOR FLOOR PANS EXCEPT TUNNEL	ALL
INTERIOR FLOOR COMPLETE CUT	\$ 1,875	INCLUDES ALL INTERIOR FLOOR COMPONENTS	ALL EXCEPT
MAIN CABIN FLOOR REPAIR SECTION (FULL) SEAT WAYFARER CPE & SEDAN ONLY	\$ 630 PER SIDE	INCLUDES FULL LENGTH PANEL FROM TOE BOARD TO BACK OF REAR	
DRIVE SHAFT TUNNEL SEAT WAYFARER CPE & SEDAN ONLY	\$ 245	REPLACES THE TUNNEL FROM FRONT FLOOR PAN TO BACK OF REAR	
TRUNK FLOOR W/SPARE TIRE WELL CUT	\$ 1,550 EA	REPLACES ENTIRE TRUNK FLOOR AS ORIGINAL	ALL EXCEPT
SPARE TIRE WELL REPLACEMENT SECTION ALL EXCEPT CUT	\$ 325 EA	REPLACES ENTIRE SPARE TIRE WELL AREA AS ORIGINAL	