

**1935 (Second Series) - 1938 Dodge & Plymouth Pickup Trucks**

**Outer Repair Panels**

<b>Part Name</b>	<b>Description</b>	<b>Price Each</b>
Door Panel, Outer Repair Section	Replaces the lower 6" of Outer Door Panel	\$ 109
Cab Corner	Replaces cab lower corner, includes reveal	\$ 196
Cab Rear Reveal	Replaces cab lower 8", includes reveal	\$ 196
Cowl Repair Section	Replaces the lower 6" of the cowl	\$ 118
Rocker, Outer	Replaces entire Outer Rocker as original	\$ 196
Side Splash Apron	Replaces Side Splash Apron as Original	\$ 392

**Inner Cab Structure Components**

Door Frame Bottom Repair Section	Replaces the bottom of the door frame	\$ 118
Sub Frame Rail	Replaces entire inner body to frame structure - one side	\$ 392
Rear Cross Member	Replaces entire rear body cross member at back of cab	\$ 196
Cab Rear Reveal Weld Strip	Provides interior welding area for exterior panel	\$ 118

**1939 - 1948 Dodge & Plymouth Pickup Trucks**

**Outer Repair Panels**

<b>Part Name</b>	<b>Description</b>	<b>Price Each</b>
Rocker, Outer	Replaces entire Outer Rocker as original	\$ 196

**Inner Cab Structure Components**

Door Frame Bottom Repair Section	Replaces the bottom of the door frame	\$ 118
Sub Frame Rail	Replaces entire inner body to frame structure - one side	\$ 392